

April 1, 2022

Scaffolding Work Done For almost 3 years, since July 2019, the Point Pinos tower with lantern room has been restored and the scaffolding removed. The gallery and safety railing have been restored. Fortunately, our 3rd order lens has remained active with the same signature it's had since 1954: Oc 4s (On more than off: 3 seconds on, 1 second off). The next work will be to replace the wall plates that were not able to be restored. There are 10 marine grade stainless steel plates, weighing about 80 pounds each. They will replace the temporary plywood soon.

